

## AIR FILTERS

The Australian Standard AS/NZS 4815-2006 requires that **air filters** be inspected every six months. The following air filters can easily be changed by the operator. Air filters for other makes and models are available, but they must be fitted by a competent technician.



Type A

**Type A HEPA Filter** to suit the following autoclaves:

- Mocom: All models
- Siltex: Baby, Pratika
- Sirona: Siroclave
- Starclave: All models
- Tecno-Gaz: All models
- W & H: LISA

Part No. AF-TYPEA.....\$49.00



Type B

**Type B HEPA Filter** to suit the following autoclaves:

- Tuttnauer: NOVA

Part No. AF-TYPEB.....\$35.00




Type C

**Type C 0.2µm HEPA Filter** to suit the following autoclaves:


- Tuttnauer: All EKA models

Part No. AF-TYPEC.....\$277.00

## STRAINERS



Midmark



Tuttnauer



Validator Plus



Siltex Strainer



Siltex Bronze Strainer

**Strainers** can stop debris from passing from the chamber into the autoclaves valves, necessitating costly repairs. Regularly replacing strainers can also help prevent water fill related errors.

Midmark Strainer..... Part No. STR-MID.....\$94.00  
 Tuttnauer Strainer..... Part No. STR-TUT.....\$26.00  
 Validator Plus Strainer..... Part No. STR-VAL.....\$37.00  
 Siltex Strainer..... Part No. STR-SIL.....\$7.00  
 Siltex Bronze Strainer..... Part No. STR-SIL-BR.....\$8.00  
 Cominox Strainer..... Part No. STR-COM.....\$18.00

## POWER CORDS



Autoclave **power cords** often get inadvertently damaged. If yours looks like it has had better days, why not replace it with a new safety tested lead? Power Cords with a right angle plug are ideal for tight locations.

240 Volt 10 amp, straight plug  
 Part No. PC-10S.....\$15.00  
 240 Volt 10 amp, right angle plug  
 Part No. PC-10R.....\$15.00  
 240 Volt 15 amp, right angle plug  
 Part No. PC-15R.....\$80.00